



# **HDI COMPACT**

## QUICK START GUIDE

For more information visit [www.polyga.com/gs](http://www.polyga.com/gs)



### 1. DOWNLOAD FLEXSCAN3D

Log in to our website at <https://www.polyga.com/my-account/> to download and install FlexScan3D.



### 2. CONNECT YOUR SCANNER

Plug in the power (12V DC) and the ethernet RJ45 cable into the scanner and your computer. Turn the scanner on.



### 3. CONFIGURE NETWORK SETTING

Run Polyga's Network Configuration Tool from the Start Menu and select the **Scanner Default** preset to change your port settings.

Click **Apply**. Click **Test** to verify the if configuration was successful. You should see the scanner information page.



### 4. ADD YOUR SCANNER

Start FlexScan3D. Under the **Scanners** tab, select **New** to add a scanner. Select your **Scanner Type** and click **OK**. Select the **Project** tab to begin scanning.

NOTE: Always power down the scanner before removing cables from the scanner.

Got questions? Contact [support@polyga.com](mailto:support@polyga.com)